

CONTRACT PRESS UPGRADES

Bodine Motor Lube Unit Replacement Package

Ref. Part No. 810-0197 for 1.88 GPH or Ref. Part No. 810-0790 for 4.66 GPH Lube System

This package replaces press lubrication systems that utilize obsolete Bodine fractional drive lube motors, which includes those with either a 10:1, 36:1 or 72:1 ratio. These motors are no longer supported by the manufacturer. Enhancements included with this replacement package include a spin-on type filtering system, blocked line detection, and a larger lube motor.

Benefits:

- Readily available spare pump and motor parts.
- Three to five times better oil filtration than the older disc design.
- Removal of oil contaminant via the disposable spin-on filter.
- Protection against blocked oil lines.
 - A flow switch will shut down the press in the event of lost oil flow. Note: this switch cannot detect broken oil lines.

Package Includes:

The lubrication unit is assembled on a steel plate that the customer mounts to the press. This unit includes:

- Lube motor and pump
- Spin-on, 25 micron filter
- Electrical installation information
- Heater and thermal relay
- Flow switch and static switch
- Plastic oil reservoir for obi's

Press Lines:

- E2, P2, P1, G1, S1, S2 and OBI

